RYZE Claim Solutions

Insured:	EL PASO RAD IB LTD	Home:	(915) 849-3716
Property:	1013 S ST VRAIN EL PASO, TX 79901		

Reference:		Business:	
Company:	HOUSING ENTERPRISE INSURANCE COMPANY		
Business:	P.O.BOX 189 CHESHIRE, CT 06410		

Claim Number: 2ALP8 **Policy Number:** HEICP-225594-158261- **Type of Loss:** Hail

Date Contacted:	12/21/2016		
Date of Loss:	11/4/2016	Date Received:	12/20/2016
Date Inspected:	1/11/2017	Date Entered:	1/19/2017 5:49 PM
Price List:	TXEP8X_JAN17 Restoration/Service/Remodel		
Estimate:	2017-01-19-1749-8		

RYZE Claim Solutions

2017-01-19-1749-8

1013 S ST VRAIN

Main Level

Roof1



3724.64 Surface Area	37.25 Number of Squares
269.00 Total Perimeter Length	95.50 Total Ridge Length

DESCRIPTION	QTY

Remove Tear off, haul and dispose of comp. shingles - Laminated	37.25 SQ
Roofing felt - 15 lb. - double coverage/low slope	37.25 SQ
Laminated - comp. shingle rfg. - w/out felt	41.00 SQ
Ridge cap - composition shingles	95.50 LF
R&R Drip edge	269.00 LF
Furnace vent - rain cap and storm collar, 5"	8.00 EA
R&R Flat roof exhaust vent / cap - gooseneck 12"	12.00 EA
R&R Flashing - pipe jack	8.00 EA
Evaporative cooler - Detach & reset	4.00 EA

NOTES:

Grand Total Areas:

0.00 SF Walls	0.00 SF Ceiling	0.00 SF Walls and Ceiling
0.00 SF Floor	0.00 SY Flooring	0.00 LF Floor Perimeter
0.00 SF Long Wall	0.00 SF Short Wall	0.00 LF Ceil. Perimeter
0.00 Floor Area	0.00 Total Area	0.00 Interior Wall Area
196.46 Exterior Wall Area	0.00 Exterior Perimeter of Walls	
3,724.64 Surface Area	37.25 Number of Squares	0.00 Total Perimeter Length
95.50 Total Ridge Length	0.00 Total Hip Length	

4

Main Level



5

Main Level