

# PAVING SERVICES AT NORTON APARTMENTS AMENDMENT #2

## A. ADDITION TO SCOPE OF WORK:

See attached map for 3' x 35' section highlighted in green.

#### **B. QUESTIONS/CLARIFICATIONS:**

## Q1. Damaged asphalt:

Q1a. How deep do they need us to mill? Are we getting to the base?

A1a. Yes- remove the portion of concrete all the way to the base.

# Q1b.Type of asphalt?

A1b. Pour Type III asphalt (hot mix), thickness should match existing, compact to approved manufacturer's density, and then use tack coat to bond new asphalt to existing asphalt.

Q2. Restripe all pavement lines: for the wheel stop: only include unit number, not the concrete wheel stop itself?

Correction- paint all wheel stops yellow and unit numbers black. Note: not all wheel stops have unit numbers.

#### C. CHANGE TO DEADLINE FOR QUOTES:


Deadline for quotes is extended to Wednesday, December 26, 2018.

## **ACKNOWLEDGEMENT OF RECEIPT OF DOCUMENTS**

All prospective contractors for the above-referenced solicitation must sign this acknowledgement form as verification of receipt of document.

NOTE: Each prospective bidder must submit this form with the submission package. Any proposals not including this form may be considered non-responsive.

Acknowledged by:	
	Company Name
	Printed Name of Authorized Company Official
Date:	Signature of Authorized Company Official



REFER TO SCOPE OF WORK TACK COAT REPAIRS. RED AREAS ARE NEAR THE FOL-LOWING LOCATIONS: PARKING SPOTS 203, 201, 701-702, 706, 506, 710, 502, 501, 601 AND (2) SPEED BUMPS. LOCATIONS ARE ALSO MARKED ONSITE.

